

FIG. 1




FIG. 2





FIG. 3

(a)



(b)




FIG. 4




FIG. 6




FIG. 5




FIG. 7




FIG. 8






FIG. 9

(a) SECTIONAL VIEW




(b) FRACTURED PORTION



9/10

FIG. 10

(a) SECTIONAL VIEW



(b) FRACTURED PORTION

LEAD SIDE

SOLDER SIDE

Bi
42 ALLOY (+Sn)






FIG. 11

(a) SECTIONAL VIEW



(b) FRACTURED PORTION

